

Repair Order History - Details

8/29/2017 2:27:43 PM

Repair Order # SYS39174
Unit: 2217 - SD (Trucks)

Central Standard Time

Unit: 2217 - SD (Trucks)			Repair Order # SYS39174			
Date / Time (In-Out)	Status	Repair Class	Serial Number	License	Meter Reading(s)	
Date In: 8/31/2015	CLOSED	In House	1FDWF37F82ED13366	939-400	72,480 Miles	
Date Out: 9/22/2015						
Time In:	Location	Repair Stage	Mechanic/Vendor			
1:09 PM	SD		13 (Girgen, Pat)			
Time Out: 1:09 PM						
Cost Date: 8/31/2015						

Repair Order History - Details

Parts								
VMRS Code	Part Number	Description	Failure Code	Qty	Cost Per	Cost	Tax	Total Cost
030-000-000 Electrical Group		CONNECTOR		1.00	\$9.87	\$9.87	\$0.68	\$10.55
040-000-000 Engine / Motor Systems Group		F8TZ61L854AA ADAPTER		1.00	\$96.57	\$96.57	\$6.64	\$103.21
040-000-000 Engine / Motor Systems Group		1C3Z3D746AA COIL		1.00	\$112.84	\$112.84	\$7.76	\$120.60
040-000-000 Engine / Motor Systems Group		METAL REPAIR COMPOUND		1.00	\$15.45	\$15.45	\$1.06	\$16.51
040-000-000 Engine / Motor Systems Group		RTV SILICON		1.00	\$6.89	\$6.89	\$0.47	\$7.36
040-000-000 Engine / Motor Systems Group		W30006 BOLT		6.00	\$5.80	\$34.80	\$2.39	\$37.19
040-000-000 Engine / Motor Systems Group		W300013 BOLT		2.00	\$3.69	\$7.38	\$0.51	\$7.89
040-000-000 Engine / Motor Systems Group		1C3Z3A717AA HOSE		1.00	\$84.75	\$84.75	\$5.83	\$90.58
040-000-000 Engine / Motor Systems Group		F81Z8287EA CLAMP		2.00	\$23.68	\$47.36	\$3.26	\$50.62
040-000-000 Engine / Motor Systems Group		F81Z6N632AA FLANGE		2.00	\$36.79	\$73.58	\$5.06	\$78.64
040-000-000 Engine / Motor Systems Group		F4TZ6R854C ADAPATER		2.00	\$13.36	\$26.72	\$1.84	\$28.56
040-000-000 Engine / Motor Systems Group		ADAPTER		1.00	\$42.06	\$42.06	\$2.89	\$44.95
040-000-000 Engine / Motor Systems Group		ADAPTER		2.00	\$46.83	\$93.66	\$6.44	\$100.10
040-000-000 Engine / Motor Systems Group		ADAPTER		1.00	\$53.50	\$53.50	\$3.68	\$57.18
040-000-000 Engine / Motor Systems Group		N300050 NUT		4.00	\$6.01	\$24.04	\$1.65	\$25.69
040-000-000 Engine / Motor Systems Group		F81Z9430AA MANIFOLD		1.00	\$211.01	\$211.01	\$14.52	\$225.53
040-000-000 Engine / Motor Systems Group		F81Z9431AA MANIFOLD		1.00	\$207.02	\$207.02	\$14.24	\$221.26
040-000-000 Engine / Motor Systems Group		F4TZ95425A BOLT		16.00	\$2.81	\$44.96	\$3.09	\$48.05
040-000-000 Engine / Motor Systems Group		F5UZ95425A BOLT		1.00	\$27.01	\$27.01	\$1.86	\$28.87
040-000-000 Engine / Motor Systems Group		3C3Z3A714CA HOSE		1.00	\$145.22	\$145.22	\$9.99	\$155.21
040-000-000 Engine / Motor Systems Group		88278 AIR FILTER		1.00	\$13.60	\$13.60	\$0.94	\$14.54
T15-000-000 Steering & Susp		HOSE		1.00	\$80.64	\$80.64	\$5.55	\$86.19
T15-000-000 Steering & Susp		HOSE		1.00	\$94.50	\$94.50	\$6.50	\$101.00
T15-000-000 Steering & Susp		HOSE		1.00	\$53.68	\$53.68	\$3.69	\$57.37

Total Parts Cost:

\$1,717.65

Repair Order History - Details

8/29/2017 2:27:43 PM

Central Standard Time

Labor										
VMRS Code Work Accomplished	Failure Code	Mechanic / Vendor Method	Date	Time In	Time Out	Hours	Rate	Cost	Tax	Total Cost
030-000-000 Electrical Group		13 (Girgen, Pat) STRAIGHT TIME	08/31/15	01:09 PM	03:39 PM	2.5	\$76.00	\$190.00	\$0.00	\$190.00
040-000-000 Engine / Motor Systems Group		13 (Girgen, Pat) STRAIGHT TIME	09/02/15	12:00 AM	02:09 PM	14.15	\$76.00	\$1,075.40	\$0.00	\$1,075.40
040-000-000 Engine / Motor Systems Group		13 (Girgen, Pat) STRAIGHT TIME	08/31/15	01:09 PM	11:59 PM	10.85	\$76.00	\$824.60	\$0.00	\$824.60
040-000-000 Engine / Motor Systems Group		13 (Girgen, Pat) STRAIGHT TIME	09/01/15	12:00 AM	11:59 PM	24	\$76.00	\$1,824.00	\$0.00	\$1,824.00
051-000-000 General Accessories		15 (Danielson, Corey) STRAIGHT TIME	08/31/15	01:09 PM	01:39 PM	0.5	\$74.00	\$37.00	\$0.00	\$37.00
T15-000-000 Steering & Susp		13 (Girgen, Pat) STRAIGHT TIME	08/31/15	01:09 PM	06:39 PM	5.5	\$76.00	\$418.00	\$0.00	\$418.00

Total Labor Cost:

\$4,369.00

Work Performed		
VMRS System	Repair Reason	Work Description
040 Engine / Motor Systems Group	Breakdown	INSPECTED AND FOUND SEVERAL EXHAUST MANIFOLD BOLTS AND STUDS SNAPPED OFF. HAD TO TEAR DOWN ENGINE TO GET TO MANIFOLDS. REMOVED MANIFOLDS AND SPEND SEVERAL HOURS EXTICATING BROKEN FASTENERS FROM BLOCK. INSTALLED NEW MANIFOLDS AND OTHER PARTS.
051 General Accessories	Routine Work	INSTALLED TELEMATICS
T15 Steering & Susp	Routine Work	INSTALLED NEW POWER STEERING LINES.
030 Electrical Group	Routine Work	REPAIRED WIRING TO CAB AND INSTALLED COVERS.
043 Exhaust System	Routine Work	

Total R/O Cost

\$6,086.65