

Repair Order History - Details

8/29/2017 2:27:43 PM

Repair Order # SYS34409
Unit: 2217 - SD (Trucks)

Central Standard Time

Unit: 2217 - SD (Trucks) Repair Order # SYS34409

Date / Time (In-Out)	Status	Repair Class	Serial Number	License	Meter Reading(s)
Date In: 5/29/2014	CLOSED	Outside Repair	1FDWF37F82ED13366	939-400	67,034 Miles
Date Out: 6/3/2014					
Time In:	Location	Repair Stage	Mechanic/Vendor		
Time Out: 10:19 AM	SD				
Cost Date: 5/29/2014					

External Work

Ernhart's Auto Center

Date: 6/3/2014

Status: Unpaid

Billing Method:

Purchased By:

Notes: REAR MAIN LEAKS AND OIL PAN RUSTED OUT. PULL ENGINE AND REPAIR AS NECESSARY. REPLACED OIL PAN, REAR MAIN SEAL, TURBO PEDESTAL, NEW OIL COOLER, WATER PUMP, WATER PUMP INLETS & OUTLETS, OIL DIPSTICK TUBE AND OTHER NECESSARY PARTS TO COMPLETE REPAIR. POWER STEERING IS NOISY. REPLACED POWER STEERING PUMP. HIGH PRESSURE OIL PUMP LEAKS. REPLACED PUMP. REASSEMBLE VEHICLE AND TEST DRIVE - OK.

Invoice #: 5324

VMRS Code: 040-000-000 Engine / Motor Systems Group

Repair Reason: Breakdown

Failure Code:

Work Description:

Work Accomplished	Item	Cost	Tax Cost	Total Cost
Labor:		\$2,228.80	\$0.00	\$2,228.80
		Total Labor:	\$0.00	\$2,228.80
Parts:	PARTS	\$3,186.66	\$218.41	\$3,405.07
		Total Part:	\$218.41	\$3,405.07
Total:	040-000-000 Engine / Motor Systems Group	\$5,415.46	\$218.41	\$5,633.87

Total R/O Cost \$5,633.87